

MiniMAC Wash				MiniMAC Profile				Value	Percent	Function
1	2	3	4	1	2	3	4			
-				4				0 - 2	0	Gobo Rotation and Swing (select gobo on ch. 3) No rotation CW rotation, slow to fast CCW rotation, fast to slow No rotation Gobo swing, slow to fast
								3 - 117	1 - 46	
								118 - 232	46 - 91	
								233 - 239	91 - 94	
								240 - 255	94 - 100	
3				5				0 - 255	0-100	Pan Left to right (128 = neutral)
-	4	-	4	-	6	-	6	0 - 255	0-100	Pan fine (LSB) Left to right
4	5	4	5	6	7	6	7	0 - 255	0-100	Tilt Up to down (128 = neutral)
-	6	-	6	-	8	-	8	0 - 255	0-100	Tilt fine (LSB) Up to down
-				-				0 - 2	0	Pan/Tilt Speed Tracking mode Fast to slow Tracking, P t S = S L O Tracking, P t S = F S t Blackout while moving
								3 - 245	1 - 96	
								246 - 248	96 - 97	
								249 - 251	98	
								252 - 255	99 - 100	
-				-				0 - 2	0	Effects Speed Tracking mode Fast to slow Blackout while moving
								3 - 251	1 - 96	
								252 - 255	97 - 100	